

HOGAN & HARTSON

COLUMBIA SQUARE
555 THIRTEENTH STREET NW
WASHINGTON, DC 20004-1109
202/637-5600

WRITER'S DIRECT DIAL NUMBER
202/637-6536

RECORDATION NO. 6129 B
DEC 30 1988 10:42 PM
6701 ROCKLEDGE DRIVE
BETHESDA, MARYLAND 20817
301/493-0030

INTERSTATE COMMERCE COMMISSION
111 SOUTH CALVERT STREET
BALTIMORE, MARYLAND 21202
301/659-2700

8300 GREENSBORO DRIVE
MCLEAN, VIRGINIA 22102
703/848-2600

Office of the Secretary
Recordations Unit
Room 2303
Interstate Commerce Commission
12th and Constitution Avenue, N.W.
Washington, D.C. 20423

ATTENTION: Ms. Mildred Lee

Dear Ms. Lee:

Enclosed are an original and one certified true copy of each of the documents described below, to be recorded pursuant to 49 U.S.C. § 11303. These documents are (1) four equipment lease agreements, dated December 15, 1988; (2) four lease supplements No. 1 dated December 30, 1988; (3) four security agreement-trust deeds, dated December 15, 1988 and (4) four security agreement-trust deed supplements No. 1 dated December 30, 1988.

The names and addresses of the parties of Pullman Leasing Trusts Nos. 88-1 through 88-4 are as follows:

(1) The parties to the Equipment Lease Agreement are:

Wilmington Trust Company,
as lessor
Rodney Square North
Wilmington, Delaware 19890
and

Pullman Leasing Company, as lessee
200 South Michigan Avenue
Chicago, Illinois 60604

Office of the Secretary
December 30, 1988
Page 2

(2) The parties to the Lease Supplement No. 1 are:

Wilmington Trust Company,
as owner-trustee
Rodney Square North
Wilmington, Delaware 19890
and

Pullman Leasing Company, as lessee
200 South Michigan Avenue
Chicago, Illinois 60604

(3) The parties to the Security Agreement-Trust Deed
are:

Wilmington Trust Company,
as owner-trustee
Rodney Square North
Wilmington, Delaware 19890
and

The Connecticut Bank and Trust Company,
National Association, as security trustee
One Constitution Plaza
Hartford, Connecticut 06115

(4) The parties to the Security Agreement-Trust Deed
Supplement No. 1 are:

Wilmington Trust Company,
as owner-trustee
Rodney Square North
Wilmington, Delaware 19890
and

The Connecticut Bank and Trust Company,
National Association, as security trustee
One Constitution Plaza
Hartford, Connecticut 06115

Office of the Secretary
December 30, 1988
Page 3

A description of the equipment covered by these documents follows:

88-1: 400 100-ton 5,850 cfc Covered Hopper Cars
250 100-ton 3,000 cfc Covered Hopper Cars
150 23,500-gallon Coiled and Insulated Tank Cars
50 30,000-gallon Non-Coiled and Non-Insulated
Tank Cars
50 20,000-gallon Coiled and Insulated Tank Cars


88-2: 941 100-ton 4,570 cfc Covered Hopper Cars

88-3: 793 100-ton 4,570 cfc Covered Hopper Cars

88-4: 794 100-ton 4,570 cfc Covered Hopper Cars
123 20,800-gallon Coiled and Insulated Tank Cars

A filing fee of \$13.00 per document is enclosed.
Please return the original and any extra copies not needed by
the Commission for recordation to the undersigned.

Sincerely,



Nancy Rosenshein
Legal Assistant

Enclosures

cc: Patrick M. Raher
Peter F. Rousselot

LEASE SUPPLEMENT NO. 1

DEC 30

1988 10 AM PM

INTERSTATE COMMERCE COMMISSION

This LEASE SUPPLEMENT NO. 1, dated December 30, 1988 between Wilmington Trust Company, a Delaware banking corporation, not individually but solely as trustee (the "Owner-Trustee") under the Trust Agreement establishing Pullman Leasing Trust No. 88-4, and Pullman Leasing Company, a Delaware corporation (the "Lessee");

W I T N E S S E T H:

The Owner-Trustee and the Lessee have heretofore entered into that certain Lease Agreement dated as of December 15, 1988 (the "Lease"). The terms used herein have the meanings specified in the Lease.

The Lease provides for the execution and delivery of a Lease Supplement substantially in the form hereof.

NOW, THEREFORE, in consideration of the premises and other good and sufficient consideration, the Owner-Trustee and the Lessee hereby agree as follows:

1. The Lessee hereby acknowledges and confirms that it has inspected and approved the following Equipment and on the date hereof the following Equipment has been unconditionally accepted by the Lessee and is now leased under the Lease.

<u>TYPE OF EQUIPMENT</u>	<u>EQUIPMENT COST PER ITEM</u>	<u>DATE ACCEPTED</u>	<u>NUMBER OF UNITS</u>	<u>MARKED AND NUMBERED</u>
100-ton 4750 cfc covered hopper cars	See attached schedule	Dec. 30, 1988	794	See attached schedule
20,800 gallon exterior coiled and insulated tank cars	\$33,663.50	Dec. 30, 1988	123	See attached schedule

The Lessee represents and warrants that the foregoing Items of Equipment are free and clear of all liens, claims and encumbrances except the Lien of the Security Agreement and except any Liens which may have been created by the Owner-Trustee. The Lessee certifies that the foregoing Items of Equipment are in good order and condition, and conform to the specifications applicable thereto, that the Lessee has no knowledge of any defect in any of the foregoing Items of Equipment with respect to design, manufacture or condition or in any other respect. The Lessee covenants that as soon as practicable but in any event not later than December 31, 1990 each Item will be labeled by means of a plate or a stencil printed in contrasting colors upon each side of the Item in letters not less than one inch in height as follows:

"Leased from Bank or Trust Company, as Trustee, and Subject to a Security Interest Recorded with the I.C.C."

2. The date of delivery and acceptance of the Equipment is the date of this Lease Supplement set forth in the opening paragraph hereof.

3. The Total Equipment Cost for the Equipment is \$20,178,877.50.

4. Any and all notices, requests, certificates and other instruments executed and delivered after the execution and delivery of this Lease Supplement may refer to the "Lease Agreement dated as of December 15, 1988", the "Lease dated as of December 15, 1988" or the "Equipment Lease dated as of December 15, 1988," or may identify the Lease in any other respect without making specific reference to this Lease Supplement, but nevertheless all such references shall be deemed to include this Lease Supplement unless the context shall otherwise require.

5. This Lease Supplement shall be construed in connection with and as part of the Lease, and all terms, conditions and covenants contained in the Lease, except as herein modified, shall be and remain in full force and effect.

6. This Lease Supplement may be executed in any number of counterparts, each executed counterpart constituting an original but all together one and the same instrument.

7. There has been no prepayment of the Rent.

IN WITNESS WHEREOF, the Trustee and the Lessee have caused this Lease Supplement to be duly executed as of the date and year first above written and to be delivered as of the date first above written.

WILMINGTON TRUST COMPANY, not individually but solely as Trustee under Pullman Leasing Trust No. 88-4

By: 
Its: _____

PULLMAN LEASING COMPANY

By: Timothy A. Hickey
Its: V.P. 

This Lease Supplement and the Lease referred to herein and the rentals and other sums due and to become due hereunder and thereunder have been assigned to and are subject to a security interest in favor of The Connecticut Bank and Trust Company, National Association, as Security Trustee under a Security Agreement-Trust Deed dated as of December 15, 1988 between said Security Trustee and the Owner-Trustee hereunder, as Debtor. Information concerning such security interest may be obtained from the Security Trustee at its address set forth in Section 21.1 of said Lease.

STATE OF ILLINOIS)
) SS:
 COUNTY OF COOK)

On this 30th day of December 1988, before me personally appeared WILLIAM B. SONOEN III, to me personally known, who being duly sworn, says that he is a ~~(+)~~ VICE PRESIDENT of WILMINGTON TRUST COMPANY, that said instrument was signed and sealed on behalf of said corporation by authority of its Board of Directors, and he acknowledged that the execution of the foregoing instrument was the free act and deed of said corporation.

Jean Horan
 Notary Public

[NOTARIAL SEAL]

My Commission Expires:

My Commission Expires July 15, 1989

STATE OF ILLINOIS)
) SS:
 COUNTY OF COOK)

On this 30th day of December 1988, before me personally appeared TERRENCE F. HEIDKAMP, to me personally known, who being by me duly sworn, says that he is a ~~(+)~~ VICE PRESIDENT of PULLMAN LEASING COMPANY, that said instrument was signed and sealed on behalf of said corporation by authority of its Board of Directors, and he acknowledged that the execution of the foregoing instrument was the free act and deed of said corporation.

Jean Horan
 Notary Public

My Commission Expires:

My Commission Expires July 15, 1989

[NOTARIAL SEAL]

NAT WEST LEVERAGED LEASE - TANK CARS

PULLMAN'S PERMANENT ASSET NUMBER	CURRENT REPORTING NUMBER	YEAR BUILT	EQUIPMENT COST
PLCI 200571	WFIX	101	33,663.50
PLCI 200572	WFIX	102	33,663.50
PLCI 200573	WFIX	103	33,663.50
PLCI 200574	WFIX	104	33,663.50
PLCI 200575	WFIX	105	33,663.50
PLCI 200576	WFIX	106	33,663.50
PLCI 200577	WFIX	107	33,663.50
PLCI 200578	WFIX	108	33,663.50
PLCI 200579	WFIX	109	33,663.50
PLCI 200580	WFIX	110	33,663.50
PLCI 200581	WFIX	111	33,663.50
PLCI 200582	WFIX	112	33,663.50
PLCI 200583	WFIX	113	33,663.50
PLCI 200584	WFIX	114	33,663.50
PLCI 200585	WFIX	115	33,663.50
PLCI 200586	WFIX	116	33,663.50
PLCI 200587	WFIX	117	33,663.50
PLCI 200588	WFIX	118	33,663.50
PLCI 200589	WFIX	119	33,663.50
PLCI 200590	WFIX	120	33,663.50
PLCI 200591	WFIX	121	33,663.50
PLCI 200592	WFIX	122	33,663.50
PLCI 200593	WFIX	123	33,663.50
PLCI 200594	WFIX	124	33,663.50
PLCI 200595	WFIX	125	33,663.50
PLCI 200596	WFIX	126	33,663.50
PLCI 200597	WFIX	127	33,663.50
PLCI 200598	WFIX	128	33,663.50
PLCI 200599	WFIX	129	33,663.50
PLCI 200600	WFIX	130	33,663.50
PLCI 200601	WFIX	131	33,663.50
PLCI 200602	WFIX	132	33,663.50
PLCI 200603	WFIX	133	33,663.50
PLCI 200604	WFIX	134	33,663.50

SCHEDULE

PULLMAN'S PERMANENT ASSET NUMBER	CURRENT REPORTING NUMBER	YEAR BUILT	EQUIPMENT COST
PLCX 200605	WFIX	135	33,663.50
PLCX 200606	WFIX	136	33,663.50
PLCX 200607	WFIX	137	33,663.50
PLCX 200608	WFIX	138	33,663.50
PLCX 200609	WFIX	139	33,663.50
PLCX 200610	WFIX	140	33,663.50
PLCX 200611	WFIX	141	33,663.50
PLCX 200612	WFIX	142	33,663.50
PLCX 200613	WFIX	143	33,663.50
PLCX 200614	WFIX	144	33,663.50
PLCX 200615	WFIX	145	33,663.50
PLCX 200616	WFIX	146	33,663.50
PLCX 200617	WFIX	147	33,663.50
PLCX 200618	WFIX	148	33,663.50
PLCX 200619	WFIX	149	33,663.50
PLCX 200620	WFIX	150	33,663.50
PLCX 200621	WFIX	151	33,663.50
PLCX 200622	WFIX	152	33,663.50
PLCX 200623	WFIX	153	33,663.50
PLCX 200624	WFIX	154	33,663.50
PLCX 200625	WFIX	155	33,663.50
PLCX 200626	WFIX	156	33,663.50
PLCX 200627	WFIX	157	33,663.50
PLCX 200628	WFIX	158	33,663.50
PLCX 200629	WFIX	159	33,663.50
PLCX 200630	WFIX	160	33,663.50
PLCX 200631	WFIX	161	33,663.50
PLCX 200632	WFIX	162	33,663.50
PLCX 200633	WFIX	164	33,663.50
PLCX 200634	WFIX	165	33,663.50
PLCX 200635	WFIX	166	33,663.50
PLCX 200636	WFIX	167	33,663.50
PLCX 200637	WFIX	168	33,663.50
PLCX 200638	WFIX	169	33,663.50
PLCX 200639	WFIX	170	33,663.50
PLCX 200640	WFIX	171	33,663.50
PLCX 200641	WFIX	172	33,663.50
PLCX 200642	WFIX	173	33,663.50

PULLMAN'S PERMANENT ASSET NUMBER	CURRENT REPORTING NUMBER	YEAR BUILT	EQUIPMENT COST
PLCI 200643	WFII	174	33,663.50
PLCI 200646	WFII	175	33,663.50
PLCI 200648	WFII	176	33,663.50
PLCI 200646	WFII	177	33,663.50
PLCI 200647	WFII	178	33,663.50
PLCI 200648	WFII	179	33,663.50
PLCI 200649	WFII	180	33,663.50
PLCI 200650	WFII	181	33,663.50
PLCI 200651	WFII	182	33,663.50
PLCI 200652	WFII	183	33,663.50
PLCI 200653	WFII	184	33,663.50
PLCI 200654	WFII	185	33,663.50
PLCI 200655	WFII	186	33,663.50
PLCI 200656	WFII	187	33,663.50
PLCI 200657	WFII	188	33,663.50
PLCI 200658	WFII	189	33,663.50
PLCI 200659	WFII	191	33,663.50
PLCI 200660	WFII	192	33,663.50
PLCI 200661	WFII	193	33,663.50
PLCI 200662	WFII	194	33,663.50
PLCI 200663	WFII	195	33,663.50
PLCI 200664	WFII	197	33,663.50
PLCI 200665	WFII	198	33,663.50
PLCI 200666	WFII	199	33,663.50
PLCI 200667	WFII	200	33,663.50
PLCI 200668	WFII	201	33,663.50
PLCI 200669	WFII	202	33,663.50
PLCI 200670	WFII	203	33,663.50
PLCI 200671	WFII	204	33,663.50
PLCI 200672	WFII	205	33,663.50
PLCI 200673	WFII	207	33,663.50
PLCI 200674	WFII	209	33,663.50
PLCI 200675	WFII	210	33,663.50
PLCI 200676	WFII	211	33,663.50
PLCI 200677	WFII	212	33,663.50
PLCI 200678	WFII	213	33,663.50
PLCI 200679	WFII	214	33,663.50
PLCI 200680	WFII	215	33,663.50

PULLMAN'S PERMANENT ASSET NUMBER	CURRENT REPORTING NUMBER	YEAR BUILT	EQUIPMENT COST
PLCI 200688	WFII	216	\$3,663.50
PLCI 200689	WFII	217	\$3,663.50
PLCI 200690	WFII	218	\$3,663.50
PLCI 200691	WFII	219	\$3,663.50
PLCI 200692	WFII	220	\$3,663.50
PLCI 200693	WFII	221	\$3,663.50
PLCI 200694	WFII	222	\$3,663.50
PLCI 200695	WFII	223	\$3,663.50
PLCI 200696	WFII	224	\$3,663.50
PLCI 200697	WFII	225	\$3,663.50
PLCI 200698	WFII	226	\$3,663.50
PLCI 200699	WFII	227	\$3,663.50
PLCI 200700	WFII	228	\$3,663.50
TOTAL			\$140,610.50

NAT WEST LEVERAGED LEASE

YEAR BUILT	NUMBER OF CAPS	COST		TOTAL COST
		PER CAP	TOTAL	
1973	130	14,370	1,868,100	
1974	104	15,514	1,613,456	
1975	1	16,967	16,967	
1978	24	20,395	489,480	
1979	290	21,697	6,292,130	
1980	237	23,454	5,530,598	
1981	8	24,942	199,536	
	794		16,038,267	

PLC	CAR NUMBER	UNION TANK	YEAR BUILT	COST
PLCI	12020	UTCI	44173	14,370
PLCI	12021	UTCI	44199	14,370
PLCI	12022	UTCI	44273	14,370
PLCI	12023	UTCI	44289	14,370
PLCI	12028	UTCI	44621	14,370
PLCI	12244	UTCI	44096	14,370
PLCI	12245	UTCI	44098	14,370
PLCI	12246	UTCI	44100	14,370
PLCI	12247	UTCI	44102	14,370
PLCI	12248	UTCI	44112	14,370
PLCI	12249	UTCI	44117	14,370
PLCI	12250	UTCI	44125	14,370
PLCI	12251	UTCI	44126	14,370
PLCI	12252	UTCI	44134	14,370
PLCI	12253	UTCI	44135	14,370
PLCI	12254	UTCI	44137	14,370
PLCI	12255	UTCI	44140	14,370
PLCI	12256	UTCI	44142	14,370
PLCI	12257	UTCI	44149	14,370
PLCI	12258	UTCI	44158	14,370
PLCI	12259	UTCI	44160	14,370
PLCI	12260	UTCI	44165	14,370
PLCI	12261	UTCI	44172	14,370
PLCI	12262	UTCI	44175	14,370
PLCI	12263	UTCI	44176	14,370
PLCI	12264	UTCI	44180	14,370
PLCI	12265	UTCI	44181	14,370
PLCI	12266	UTCI	44185	14,370
PLCI	12267	UTCI	44189	14,370
PLCI	12268	UTCI	44194	14,370
PLCI	12269	UTCI	44197	14,370
PLCI	12270	UTCI	44200	14,370
PLCI	12271	UTCI	44203	14,370
PLCI	12272	UTCI	44206	14,370
PLCI	12273	UTCI	44208	14,370
PLCI	12274	UTCI	44216	14,370
PLCI	12275	UTCI	44219	14,370
PLCI	12276	UTCI	44226	14,370

PLC	UNION TANK	YEAR			
CAP NUMBER	CAP NUMBER	BUILT	COST		
PLCX	12277	UTCX	44234	1973	14,370
PLCX	12278	UTCX	44242	1973	14,370
PLCX	12279	UTCX	44245	1973	14,370
PLCX	12280	UTCX	44248	1973	14,370
PLCX	12281	UTCX	44253	1973	14,370
PLCX	12282	UTCX	44256	1973	14,370
PLCX	12283	UTCX	44263	1973	14,370
PLCX	12284	UTCX	44267	1973	14,370
PLCX	12285	UTCX	44268	1973	14,370
PLCX	12286	UTCX	44270	1973	14,370
PLCX	12287	UTCX	44271	1973	14,370
PLCX	12288	UTCX	44274	1973	14,370
PLCX	12289	UTCX	44281	1973	14,370
PLCX	12290	UTCX	44285	1973	14,370
PLCX	12291	UTCX	44286	1973	14,370
PLCX	12292	UTCX	44287	1973	14,370
PLCX	12293	UTCX	44288	1973	14,370
PLCX	12294	UTCX	44290	1973	14,370
PLCX	12295	UTCX	44291	1973	14,370
PLCX	12296	UTCX	44292	1973	14,370
PLCX	12297	UTCX	44295	1973	14,370
PLCX	12303	UTCX	44530	1973	14,370
PLCX	12304	UTCX	44542	1973	14,370
PLCX	12305	UTCX	44544	1973	14,370
PLCX	12306	UTCX	44548	1973	14,370
PLCX	12307	UTCX	44551	1973	14,370
PLCX	12308	UTCX	44554	1973	14,370
PLCX	12309	UTCX	44555	1973	14,370
PLCX	12310	UTCX	44556	1973	14,370
PLCX	12311	UTCX	44558	1973	14,370
PLCX	12312	UTCX	44561	1973	14,370
PLCX	12313	UTCX	44565	1973	14,370
PLCX	12314	UTCX	44567	1973	14,370
PLCX	12315	UTCX	44568	1973	14,370
PLCX	12316	UTCX	44570	1973	14,370
PLCX	12317	UTCX	44571	1973	14,370
PLCX	12318	UTCX	44572	1973	14,370
PLCX	12319	UTCX	44574	1973	14,370

PLC	UNION TAN	YEAR			
CAR NUMBER	CAR NUMBER	BUILT	COST		
PLCX	12320	UTCX	44575	1973	14,370
PLCX	12321	UTCX	44577	1973	14,370
PLCX	12322	UTCX	44578	1973	14,370
PLCX	12323	UTCX	44579	1973	14,370
PLCX	12324	UTCX	44580	1973	14,370
PLCX	12325	UTCX	44581	1973	14,370
PLCX	12326	UTCX	44583	1973	14,370
PLCX	12327	UTCX	44584	1973	14,370
PLCX	12328	UTCX	44590	1973	14,370
PLCX	12329	UTCX	44593	1973	14,370
PLCX	12330	UTCX	44594	1973	14,370
PLCX	12331	UTCX	44595	1973	14,370
PLCX	12332	UTCX	44601	1973	14,370
PLCX	12333	UTCX	44602	1973	14,370
PLCX	12334	UTCX	44604	1973	14,370
PLCX	12335	UTCX	44607	1973	14,370
PLCX	12336	UTCX	44608	1973	14,370
PLCX	12337	UTCX	44610	1973	14,370
PLCX	12338	UTCX	44611	1973	14,370
PLCX	12339	UTCX	44612	1973	14,370
PLCX	12340	UTCX	44615	1973	14,370
PLCX	12341	UTCX	44617	1973	14,370
PLCX	12342	UTCX	44619	1973	14,370
PLCX	12343	UTCX	44620	1973	14,370
PLCX	12344	UTCX	44622	1973	14,370
PLCX	12345	UTCX	44623	1973	14,370
PLCX	12346	UTCX	44624	1973	14,370
PLCX	12347	UTCX	44625	1973	14,370
PLCX	12348	UTCX	44627	1973	14,370
PLCX	12349	UTCX	44632	1973	14,370
PLCX	12350	UTCX	44633	1973	14,370
PLCX	12351	UTCX	44637	1973	14,370
PLCX	12352	UTCX	44153	1973	14,370
PLCX	12354	UTCX	44232	1973	14,370
PLCX	12366	UTCX	44099	1973	14,370
PLCX	12367	UTCX	44101	1973	14,370
PLCX	12368	UTCX	44195	1973	14,370
PLCX	12369	UTCX	44109	1973	14,370

PLC	CAR NUMBER	UNION NAME	CAR NUMBER	YEAR BUILT	COST
PLCX	12570	UTCX	44121	1973	14,370
PLCX	12571	UTCX	44123	1973	14,370
PLCX	12572	UTCX	44143	1973	14,370
PLCX	12573	UTCX	44144	1973	14,370
PLCX	12574	UTCX	44145	1973	14,370
PLCX	12576	UTCX	44148	1973	14,370
PLCX	12577	UTCX	44151	1973	14,370
PLCX	12578	UTCX	44152	1973	14,370
PLCX	12579	UTCX	44154	1973	14,370
PLCX	12580	UTCX	44155	1973	14,370
PLCX	12581	UTCX	44161	1973	14,370
PLCX	12582	UTCX	44162	1973	14,370
PLCX	12583	UTCX	44163	1973	14,370
PLCX	12584	UTCX	44164	1973	14,370
PLCX	12585	UTCX	44166	1973	14,370
PLCX	12586	UTCX	44167	1973	14,370

1,868,100

PLC	CAP NUMBER	UNION TAN	YEAR BUILT	COST
PLCX	12029	UTC1	45939	15,514
PLCX	12030	UTC1	45940	15,514
PLCX	12031	UTC1	45997	15,514
PLCX	12141	UTC1	44298	15,514
PLCX	12142	UTC1	44317	15,514
PLCX	12143	UTC1	44351	15,514
PLCX	12144	UTC1	44373	15,514
PLCX	12156	UTC1	45324	15,514
PLCX	12157	UTC1	45800	15,514
PLCX	12158	UTC1	45805	15,514
PLCX	12159	UTC1	45810	15,514
PLCX	12160	UTC1	45812	15,514
PLCX	12161	UTC1	45815	15,514
PLCX	12162	UTC1	45817	15,514
PLCX	12163	UTC1	45933	15,514
PLCX	12164	UTC1	45934	15,514
PLCX	12165	UTC1	45936	15,514
PLCX	12166	UTC1	45947	15,514
PLCX	12167	UTC1	45951	15,514
PLCX	12168	UTC1	45952	15,514
PLCX	12169	UTC1	45953	15,514
PLCX	12170	UTC1	45954	15,514
PLCX	12171	UTC1	45983	15,514
PLCX	12172	UTC1	45985	15,514
PLCX	12173	UTC1	45993	15,514
PLCX	12174	UTC1	45996	15,514
PLCX	12175	UTC1	45998	15,514
PLCX	12298	UTC1	44296	15,514
PLCX	12299	UTC1	44341	15,514
PLCX	12300	UTC1	44360	15,514
PLCX	12301	UTC1	44366	15,514
PLCX	12302	UTC1	44384	15,514
PLCX	12411	UTC1	45925	15,514
PLCX	12412	UTC1	45935	15,514
PLCX	12413	UTC1	45942	15,514
PLCX	12414	UTC1	45945	15,514
PLCX	12415	UTC1	45949	15,514
PLCX	12416	UTC1	45956	15,514

PLC	CAR NUMBER	UNION TANK	YEAR	BUILT	COST
		CAR NUMBER			
PLCX	12417	UTCI	45971	1974	15,514
PLCX	12418	UTCI	45974	1974	15,514
PLCX	12419	UTCI	45979	1974	15,514
PLCX	12420	UTCI	45982	1974	15,514
PLCX	12421	UTCI	45987	1974	15,514
PLCX	12422	UTCI	45991	1974	15,514
PLCX	12423	UTCI	45999	1974	15,514
PLCX	12503	UTCI	45802	1974	15,514
PLCX	12504	UTCI	45806	1974	15,514
PLCX	12505	UTCI	45807	1974	15,514
PLCX	12506	UTCI	45808	1974	15,514
PLCX	12507	UTCI	45813	1974	15,514
PLCX	12509	UTCI	45966	1974	15,514
PLCX	12510	UTCI	45986	1974	15,514
PLCX	12515	UTCI	44353	1974	15,514
PLCX	12660	UTCI	45801	1974	15,514
PLCX	12661	UTCI	45804	1974	15,514
PLCX	12662	UTCI	45811	1974	15,514
PLCX	12663	UTCI	45814	1974	15,514
PLCX	12973	UTCI	44362	1974	15,514
PLCX	12974	UTCI	45803	1974	15,514
PLCX	12975	UTCI	45809	1974	15,514
PLCX	12984	UTCI	44339	1974	15,514
PLCX	12988	UTCI	45944	1974	15,514
PLCX	12989	UTCI	45968	1974	15,514
PLCX	13978	UTCI	45816	1974	15,514
PLCX	25543	UTCI	45821	1974	15,514
PLCX	25544	UTCI	45822	1974	15,514
PLCX	25546	UTCI	45824	1974	15,514
PLCX	25547	UTCI	45825	1974	15,514
PLCX	25548	UTCI	45826	1974	15,514
PLCX	25549	UTCI	45827	1974	15,514
PLCX	25550	UTCI	45828	1974	15,514
PLCX	25551	UTCI	45829	1974	15,514
PLCX	25552	UTCI	45830	1974	15,514
PLCX	25553	UTCI	45831	1974	15,514
PLCX	25554	UTCI	45832	1974	15,514
PLCX	25555	UTCI	45833	1974	15,514

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCX 25556	UTCX 45834	1974	15,514
PLCX 25557	UTCX 45835	1974	15,514
PLCX 25558	UTCX 45837	1974	15,514
PLCX 25559	UTCX 45838	1974	15,514
PLCX 25560	UTCX 45841	1974	15,514
PLCX 25561	UTCX 45843	1974	15,514
PLCX 25562	UTCX 45844	1974	15,514
PLCX 25563	UTCX 45845	1974	15,514
PLCX 25564	UTCX 45846	1974	15,514
PLCX 25565	UTCX 45847	1974	15,514
PLCX 25566	UTCX 45848	1974	15,514
PLCX 25567	UTCX 45849	1974	15,514
PLCX 25568	UTCX 45850	1974	15,514
PLCX 25569	UTCX 45852	1974	15,514
PLCX 25570	UTCX 45855	1974	15,514
PLCX 25571	UTCX 45856	1974	15,514
PLCX 25572	UTCX 45857	1974	15,514
PLCX 25573	UTCX 45858	1974	15,514
PLCX 25575	UTCX 45860	1974	15,514
PLCX 25576	UTCX 45861	1974	15,514
PLCX 25577	UTCX 45862	1974	15,514
PLCX 25578	UTCX 45863	1974	15,514
PLCX 25579	UTCX 45865	1974	15,514
PLCX 25580	UTCX 45866	1974	15,514
PLCX 25581	UTCX 45868	1974	15,514
PLCX 25582	UTCX 45871	1974	15,514
PLCX 25583	UTCX 45872	1974	15,514
PLCX 25584	UTCX 45873	1974	15,514

1,613,456

PLC CAP NUMBER	UNION TANK CAP NUMBER	YEAR BUILT	COST		
PLCX	12145	UTCX	44764	1975	16,967

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCI 17149	UTCI 45301	1978	20,395
PLCI 17149	UTCI 45306	1978	20,395
PLCI 17150	UTCI 45307	1978	20,395
PLCI 17151	UTCI 45309	1978	20,395
PLCI 17152	UTCI 45314	1978	20,395
PLCI 17153	UTCI 45315	1978	20,395
PLCI 17154	UTCI 45318	1978	20,395
PLCI 17155	UTCI 45321	1978	20,395
PLCI 17806	UTCI 45352	1978	20,395
PLCI 17910	UTCI 45460	1978	20,395
PLCI 17919	UTCI 45470	1978	20,395
PLCI 13957	UTCI 45275	1978	20,395
PLCI 13958	UTCI 45276	1978	20,395
PLCI 13959	UTCI 45277	1978	20,395
PLCI 13960	UTCI 45278	1978	20,395
PLCI 13961	UTCI 45279	1978	20,395
PLCI 13962	UTCI 45280	1978	20,395
PLCI 13963	UTCI 45281	1978	20,395
PLCI 13964	UTCI 45282	1978	20,395
PLCI 13965	UTCI 45283	1978	20,395
PLCI 13966	UTCI 45285	1978	20,395
PLCI 13967	UTCI 45286	1978	20,395
PLCI 13968	UTCI 45287	1978	20,395
PLCI 13969	UTCI 45288	1978	20,395

489,480

PLC	CAR NUMBER	UNION TAND	CAR NUMBER	YEAR BUILT	COST
PLCX	12007	UTCX	43371	1979	21,697
PLCX	12008	UTCX	43375	1979	21,697
PLCX	12009	UTCX	43385	1979	21,697
PLCX	12010	UTCX	43386	1979	21,697
PLCX	12011	UTCX	43389	1979	21,697
PLCX	12012	UTCX	43391	1979	21,697
PLCX	12013	UTCX	43392	1979	21,697
PLCX	12014	UTCX	43393	1979	21,697
PLCX	12015	UTCX	43396	1979	21,697
PLCX	12016	UTCX	43398	1979	21,697
PLCX	12017	UTCX	43399	1979	21,697
PLCX	12018	UTCX	43681	1979	21,697
PLCX	12019	UTCX	43691	1979	21,697
PLCX	12024	UTCX	45235	1979	21,697
PLCX	12027	UTCX	43401	1979	21,697
PLCX	12034	UTCX	45199	1979	21,697
PLCX	12122	UTCX	43652	1979	21,697
PLCX	12123	UTCX	43657	1979	21,697
PLCX	12124	UTCX	43660	1979	21,697
PLCX	12125	UTCX	43662	1979	21,697
PLCX	12126	UTCX	43671	1979	21,697
PLCX	12127	UTCX	43672	1979	21,697
PLCX	12128	UTCX	43678	1979	21,697
PLCX	12129	UTCX	43686	1979	21,697
PLCX	12130	UTCX	43687	1979	21,697
PLCX	12131	UTCX	43689	1979	21,697
PLCX	12132	UTCX	43693	1979	21,697
PLCX	12133	UTCX	43702	1979	21,697
PLCX	12134	UTCX	43703	1979	21,697
PLCX	12135	UTCX	43707	1979	21,697
PLCX	12136	UTCX	43715	1979	21,697
PLCX	12137	UTCX	43740	1979	21,697
PLCX	12138	UTCX	43741	1979	21,697
PLCX	12139	UTCX	43742	1979	21,697
PLCX	12200	UTCX	43358	1979	21,697
PLCX	12202	UTCX	42361	1979	21,697
PLCX	12219	UTCX	43364	1979	21,697
PLCX	12211	UTCX	43368	1979	21,697

PLC	UNION TANK	YEAR BUILT	COST		
CAP NUMBER	CAP NUMBER				
PLCI	12212	UTCI	43369	1979	21,697
PLCI	12213	UTCI	43370	1979	21,697
PLCI	12214	UTCI	43379	1979	21,697
PLCI	12215	UTCI	43380	1979	21,697
PLCI	12216	UTCI	43384	1979	21,697
PLCI	12217	UTCI	43387	1979	21,697
PLCI	12218	UTCI	43388	1979	21,697
PLCI	12219	UTCI	43390	1979	21,697
PLCI	12220	UTCI	43394	1979	21,697
PLCI	12221	UTCI	43395	1979	21,697
PLCI	12222	UTCI	43397	1979	21,697
PLCI	12223	UTCI	43406	1979	21,697
PLCI	12224	UTCI	43407	1979	21,697
PLCI	12225	UTCI	43410	1979	21,697
PLCI	12226	UTCI	43412	1979	21,697
PLCI	12227	UTCI	43418	1979	21,697
PLCI	12228	UTCI	43419	1979	21,697
PLCI	12229	UTCI	43426	1979	21,697
PLCI	12230	UTCI	43427	1979	21,697
PLCI	12231	UTCI	43429	1979	21,697
PLCI	12232	UTCI	43431	1979	21,697
PLCI	12233	UTCI	43433	1979	21,697
PLCI	12234	UTCI	43668	1979	21,697
PLCI	12235	UTCI	43673	1979	21,697
PLCI	12236	UTCI	43675	1979	21,697
PLCI	12237	UTCI	43690	1979	21,697
PLCI	12238	UTCI	43713	1979	21,697
PLCI	12239	UTCI	43716	1979	21,697
PLCI	12240	UTCI	43722	1979	21,697
PLCI	12241	UTCI	43724	1979	21,697
PLCI	12242	UTCI	43743	1979	21,697
PLCI	12354	UTCI	45053	1979	21,697
PLCI	12355	UTCI	45055	1979	21,697
PLCI	12356	UTCI	45056	1979	21,697
PLCI	12357	UTCI	45057	1979	21,697
PLCI	12358	UTCI	45058	1979	21,697
PLCI	12359	UTCI	45085	1979	21,697
PLCI	12360	UTCI	45086	1979	21,697

PLC	CAR NUMBER	UNION TAN	YEAR CAR NUMBER	BUILT	COST
PLCI	12161	UTCI	45087	1979	21,697
PLCI	12162	UTCI	45089	1979	21,697
PLCI	12363	UTCI	45090	1979	21,697
PLCI	12364	UTCI	45093	1979	21,697
PLCI	12365	UTCI	45094	1979	21,697
PLCI	12366	UTCI	45095	1979	21,697
PLCI	12367	UTCI	45096	1979	21,697
PLCI	12368	UTCI	45097	1979	21,697
PLCI	12369	UTCI	45098	1979	21,697
PLCI	12370	UTCI	45099	1979	21,697
PLCI	12371	UTCI	45101	1979	21,697
PLCI	12372	UTCI	45102	1979	21,697
PLCI	12373	UTCI	45103	1979	21,697
PLCI	12374	UTCI	45106	1979	21,697
PLCI	12375	UTCI	45109	1979	21,697
PLCI	12376	UTCI	45110	1979	21,697
PLCI	12377	UTCI	45112	1979	21,697
PLCI	12378	UTCI	45113	1979	21,697
PLCI	12379	UTCI	45114	1979	21,697
PLCI	12380	UTCI	45115	1979	21,697
PLCI	12381	UTCI	45116	1979	21,697
PLCI	12382	UTCI	45118	1979	21,697
PLCI	12383	UTCI	45147	1979	21,697
PLCI	12384	UTCI	45182	1979	21,697
PLCI	12385	UTCI	45187	1979	21,697
PLCI	12386	UTCI	45198	1979	21,697
PLCI	12387	UTCI	45216	1979	21,697
PLCI	12388	UTCI	45222	1979	21,697
PLCI	12389	UTCI	45224	1979	21,697
PLCI	12390	UTCI	45232	1979	21,697
PLCI	12391	UTCI	45234	1979	21,697
PLCI	12392	UTCI	45237	1979	21,697
PLCI	12393	UTCI	45241	1979	21,697
PLCI	12394	UTCI	45242	1979	21,697
PLCI	12395	UTCI	45243	1979	21,697
PLCI	12396	UTCI	45244	1979	21,697
PLCI	12397	UTCI	45246	1979	21,697
PLCI	12398	UTCI	45247	1979	21,697

PLC CAR NUMBER	UNION TAN CAR NUMBER	YEAR BUILT	COST
PLCI 12399	UTCI 45249	1979	21,697
PLCI 12400	UTCI 45251	1979	21,697
PLCI 12401	UTCI 45256	1979	21,697
PLCI 12402	UTCI 45258	1979	21,697
PLCI 12403	UTCI 45261	1979	21,697
PLCI 12404	UTCI 45262	1979	21,697
PLCI 12405	UTCI 45263	1979	21,697
PLCI 12406	UTCI 45265	1979	21,697
PLCI 12407	UTCI 45266	1979	21,697
PLCI 12408	UTCI 45267	1979	21,697
PLCI 12409	UTCI 45273	1979	21,697
PLCI 12410	UTCI 45274	1979	21,697
PLCI 12450	UTCI 45111	1979	21,697
PLCI 12508	UTCI 45221	1979	21,697
PLCI 12511	UTCI 45088	1979	21,697
PLCI 12551	UTCI 43400	1979	21,697
PLCI 12552	UTCI 43403	1979	21,697
PLCI 12553	UTCI 43404	1979	21,697
PLCI 12554	UTCI 43421	1979	21,697
PLCI 12555	UTCI 43680	1979	21,697
PLCI 12556	UTCI 43697	1979	21,697
PLCI 12557	UTCI 43704	1979	21,697
PLCI 12558	UTCI 43706	1979	21,697
PLCI 12559	UTCI 43712	1979	21,697
PLCI 12560	UTCI 43714	1979	21,697
PLCI 12561	UTCI 43728	1979	21,697
PLCI 12562	UTCI 43729	1979	21,697
PLCI 12563	UTCI 43744	1979	21,697
PLCI 12646	UTCI 45044	1979	21,697
PLCI 12647	UTCI 45046	1979	21,697
PLCI 12648	UTCI 45048	1979	21,697
PLCI 12649	UTCI 45050	1979	21,697
PLCI 12650	UTCI 45051	1979	21,697
PLCI 12651	UTCI 45052	1979	21,697
PLCI 12653	UTCI 45100	1979	21,697
PLCI 12654	UTCI 45104	1979	21,697
PLCI 12655	UTCI 45105	1979	21,697
PLCI 12656	UTCI 45107	1979	21,697

FLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCX 12657	UTCX 45108	1979	21,697
PLCX 12658	UTCX 45229	1979	21,697
PLCX 12659	UTCX 45236	1979	21,697
PLCX 12660	UTCX 210001	1979	21,697
PLCX 12741	UTCX 43460	1979	21,697
PLCX 12742	UTCX 43470	1979	21,697
PLCX 12743	UTCX 43474	1979	21,697
PLCX 12744	UTCX 43484	1979	21,697
PLCX 12745	UTCX 43487	1979	21,697
PLCX 12746	UTCX 43509	1979	21,697
PLCX 12747	UTCX 43511	1979	21,697
PLCX 12748	UTCX 43512	1979	21,697
PLCX 12749	UTCX 43515	1979	21,697
PLCX 12750	UTCX 43536	1979	21,697
PLCX 12751	UTCX 43539	1979	21,697
PLCX 12752	UTCX 43543	1979	21,697
PLCX 12753	UTCX 43550	1979	21,697
PLCX 12754	UTCX 43554	1979	21,697
PLCX 12755	UTCX 43556	1979	21,697
PLCX 12756	UTCX 43582	1979	21,697
PLCX 12757	UTCX 43590	1979	21,697
PLCX 12758	UTCX 43594	1979	21,697
PLCX 12759	UTCX 43599	1979	21,697
PLCX 12760	UTCX 43609	1979	21,697
PLCX 12761	UTCX 43618	1979	21,697
PLCX 12762	UTCX 43620	1979	21,697
PLCX 12763	UTCX 43625	1979	21,697
PLCX 12764	UTCX 43633	1979	21,697
PLCX 12765	UTCX 43636	1979	21,697
PLCX 12779	UTCX 45120	1979	21,697
PLCX 13877	UTCX 45135	1979	21,697
PLCX 13878	UTCX 45124	1979	21,697
PLCX 13879	UTCX 45125	1979	21,697
PLCX 13900	UTCX 45126	1979	21,697
PLCX 13901	UTCX 45127	1979	21,697
PLCX 13902	UTCX 45128	1979	21,697
PLCX 13903	UTCX 45130	1979	21,697
PLCX 13904	UTCX 45131	1979	21,697

PLC	CAR NUMBER	UNION TAMP	YEAR BUILT	COST
PLCX	13905	UTCX	45133	1979
PLCX	13906	UTCX	45134	1979
PLCX	13907	UTCX	45135	1979
PLCX	13908	UTCX	45136	1979
PLCX	13909	UTCX	45137	1979
PLCX	13910	UTCX	45138	1979
PLCX	13911	UTCX	45139	1979
PLCX	13912	UTCX	45141	1979
PLCX	13913	UTCX	45142	1979
PLCX	13914	UTCX	45143	1979
PLCX	13915	UTCX	45144	1979
PLCX	13916	UTCX	45145	1979
PLCX	13917	UTCX	45154	1979
PLCX	13918	UTCX	45155	1979
PLCX	13919	UTCX	45156	1979
PLCX	13920	UTCX	45157	1979
PLCX	13921	UTCX	45159	1979
PLCX	13922	UTCX	45160	1979
PLCX	13923	UTCX	45161	1979
PLCX	13924	UTCX	45163	1979
PLCX	13925	UTCX	45164	1979
PLCX	13926	UTCX	45167	1979
PLCX	13927	UTCX	45168	1979
PLCX	13928	UTCX	45170	1979
PLCX	13929	UTCX	45171	1979
PLCX	13930	UTCX	45172	1979
PLCX	13931	UTCX	45174	1979
PLCX	13932	UTCX	45175	1979
PLCX	13933	UTCX	45177	1979
PLCX	13934	UTCX	45179	1979
PLCX	13935	UTCX	45180	1979
PLCX	13936	UTCX	45184	1979
PLCX	13937	UTCX	45186	1979
PLCX	13938	UTCX	45189	1979
PLCX	13939	UTCX	45192	1979
PLCX	13940	UTCX	45193	1979
PLCX	13941	UTCX	45194	1979
PLCX	13942	UTCX	45195	1979

PLC	CAR NUMBER	UNION TANK CAP NUMBER	YEAR BUILT	COST	
PLCI	13943	UTCI	45196	1979	21,697
PLCI	13944	UTCI	45197	1979	21,697
PLCI	13945	UTCI	45200	1979	21,697
PLCI	13946	UTCI	45201	1979	21,697
PLCI	13947	UTCI	45202	1979	21,697
PLCI	13948	UTCI	45203	1979	21,697
PLCI	13949	UTCI	45204	1979	21,697
PLCI	13950	UTCI	45205	1979	21,697
PLCI	13951	UTCI	45206	1979	21,697
PLCI	13952	UTCI	45207	1979	21,697
PLCI	13953	UTCI	45208	1979	21,697
PLCI	13954	UTCI	45209	1979	21,697
PLCI	13955	UTCI	45210	1979	21,697
PLCI	13956	UTCI	45211	1979	21,697
PLCI	25503	UTCI	43415	1979	21,697
PLCI	25504	UTCI	43420	1979	21,697
PLCI	25505	UTCI	43666	1979	21,697
PLCI	25506	UTCI	43730	1979	21,697
PLCI	25507	UTCI	43745	1979	21,697
PLCI	25508	UTCI	43746	1979	21,697
PLCI	25509	UTCI	43747	1979	21,697
PLCI	25510	UTCI	43748	1979	21,697
PLCI	25511	UTCI	43749	1979	21,697
PLCI	25526	UTCI	45045	1979	21,697
PLCI	25527	UTCI	45047	1979	21,697
PLCI	25528	UTCI	45049	1979	21,697
PLCI	25529	UTCI	45054	1979	21,697
PLCI	25530	UTCI	45059	1979	21,697
PLCI	25531	UTCI	45092	1979	21,697
PLCI	25532	UTCI	45117	1979	21,697
PLCI	25533	UTCI	45129	1979	21,697
PLCI	25534	UTCI	45183	1979	21,697
PLCI	25535	UTCI	45213	1979	21,697
PLCI	25536	UTCI	45219	1979	21,697
PLCI	25652	UTCI	43350	1979	21,697
PLCI	25654	UTCI	43355	1979	21,697
PLCI	25655	UTCI	43359	1979	21,697
PLCI	25656	UTCI	43360	1979	21,697

PLC	CAR NUMBER	UNION TANK	YEAR BUILT	COST
	CAR NUMBER	CAR NUMBER		
PLCI	25457	UTCX	43363	1979
PLCI	25458	UTCX	43373	1979
PLCI	25459	UTCX	43376	1979
PLCI	25660	UTCX	43381	1979
PLCI	25661	UTCX	43383	1979
PLCI	25662	UTCX	43402	1979
PLCI	25663	UTCX	43408	1979
PLCI	25664	UTCX	43434	1979
PLCI	25665	UTCX	43451	1979
PLCI	25666	UTCX	43452	1979
PLCI	25667	UTCX	43454	1979
PLCI	25668	UTCX	43456	1979
PLCI	25669	UTCX	43457	1979
PLCI	25670	UTCX	43458	1979
PLCI	25671	UTCX	43459	1979
PLCI	25672	UTCX	43463	1979
PLCI	25673	UTCX	43467	1979
PLCI	25674	UTCX	43468	1979
PLCI	25675	UTCX	43471	1979
PLCI	25676	UTCX	43473	1979
PLCI	25677	UTCX	43475	1979
PLCI	25678	UTCX	43482	1979
PLCI	25679	UTCX	43485	1979
PLCI	25680	UTCX	43492	1979

6,292,130

=====

PLC	CAR NUMBER	UNION TANK CAP NUMBER	YEAR BUILT	COST
PLCX	12003	UTCX	43053	1980
PLCX	12005	UTCX	43025	1980
PLCX	12006	UTCX	43040	1980
PLCX	12025	UTCX	43115	1980
PLCX	12026	UTCX	43179	1980
PLCX	12032	UTLX	220047	1980
PLCX	12035	UTLX	220094	1980
PLCX	12086	UTCX	43055	1980
PLCX	12087	UTCX	43056	1980
PLCX	12088	UTCX	43057	1980
PLCX	12089	UTCX	43058	1980
PLCX	12090	UTCX	43059	1980
PLCX	12091	UTCX	43060	1980
PLCX	12092	UTCX	43061	1980
PLCX	12093	UTCX	43062	1980
PLCX	12094	UTCX	43063	1980
PLCX	12095	UTCX	43065	1980
PLCX	12096	UTCX	43066	1980
PLCX	12097	UTCX	43067	1980
PLCX	12098	UTCX	43068	1980
PLCX	12099	UTCX	43069	1980
PLCX	12100	UTCX	43070	1980
PLCX	12101	UTCX	43071	1980
PLCX	12102	UTCX	43072	1980
PLCX	12103	UTCX	43073	1980
PLCX	12104	UTCX	43074	1980
PLCX	12105	UTCX	43075	1980
PLCX	12106	UTCX	43076	1980
PLCX	12107	UTCX	43077	1980
PLCX	12108	UTCX	43078	1980
PLCX	12109	UTCX	43079	1980
PLCX	12110	UTCX	43978	1980
PLCX	12111	UTCX	43983	1980
PLCX	12112	UTCX	43985	1980
PLCX	12113	UTCX	43988	1980
PLCX	12114	UTCX	43989	1980
PLCX	12115	UTCX	43990	1980
PLCX	12116	UTCX	43991	1980

PLC	UNION TANK	YEAR			
CAR NUMBER	CAR NUMBER	BUILT	COST		
PLCX	12117	UTCX	43999	1980	23,454
PLCX	12118	UTCX	44944	1980	23,454
PLCX	12119	UTCX	44946	1980	23,454
PLCX	12120	UTCX	44948	1980	23,454
PLCX	12121	UTCX	44970	1980	23,454
PLCX	12140	UTCX	43967	1980	23,454
PLCX	12146	UTCX	44982	1980	23,454
PLCX	12147	UTCX	44987	1980	23,454
PLCX	12176	UTCX	43011	1980	23,454
PLCX	12177	UTCX	43014	1980	23,454
PLCX	12178	UTCX	43015	1980	23,454
PLCX	12179	UTCX	43021	1980	23,454
PLCX	12180	UTCX	43022	1980	23,454
PLCX	12181	UTCX	43083	1980	23,454
PLCX	12182	UTCX	43084	1980	23,454
PLCX	12183	UTCX	43087	1980	23,454
PLCX	12184	UTCX	43088	1980	23,454
PLCX	12185	UTCX	43089	1980	23,454
PLCX	12186	UTCX	43090	1980	23,454
PLCX	12187	UTCX	43096	1980	23,454
PLCX	12188	UTCX	43099	1980	23,454
PLCX	12189	UTCX	43103	1980	23,454
PLCX	12190	UTCX	43119	1980	23,454
PLCX	12191	UTCX	43120	1980	23,454
PLCX	12192	UTCX	43123	1980	23,454
PLCX	12193	UTCX	43124	1980	23,454
PLCX	12194	UTCX	43125	1980	23,454
PLCX	12195	UTCX	43127	1980	23,454
PLCX	12196	UTCX	43130	1980	23,454
PLCX	12197	UTCX	43138	1980	23,454
PLCX	12198	UTCX	43140	1980	23,454
PLCX	12199	UTCX	43147	1980	23,454
PLCX	12200	UTCX	43149	1980	23,454
PLCX	12201	UTCX	43151	1980	23,454
PLCX	12202	UTCX	43159	1980	23,454
PLCX	12203	UTCX	43161	1980	23,454
PLCX	12204	UTCX	43167	1980	23,454
PLCX	12205	UTCX	43174	1980	23,454

PLC	UNION TARD	YEAR			
CAR NUMBER	CAR NUMBER	BUILT	COST		
PLCI	12206	UTCI	43176	1980	23,454
PLCI	12207	UTCI	43223	1980	23,454
PLCI	12243	UTCI	43997	1980	23,454
PLCI	12352	UTCI	44962	1980	23,454
PLCI	12353	UTCI	44969	1980	23,454
PLCI	12424	UTCI	808540	1980	23,454
PLCI	12425	UTCI	808541	1980	23,454
PLCI	12426	UTCI	808542	1980	23,454
PLCI	12427	UTCI	808543	1980	23,454
PLCI	12428	UTCI	808544	1980	23,454
PLCI	12429	UTCI	808545	1980	23,454
PLCI	12430	UTCI	808546	1980	23,454
PLCI	12431	UTCI	808547	1980	23,454
PLCI	12432	UTCI	808548	1980	23,454
PLCI	12433	UTCI	808549	1980	23,454
PLCI	12434	UTCI	808550	1980	23,454
PLCI	12435	UTCI	808551	1980	23,454
PLCI	12436	UTCI	808552	1980	23,454
PLCI	12437	UTCI	808553	1980	23,454
PLCI	12438	UTCI	808554	1980	23,454
PLCI	12439	UTCI	808555	1980	23,454
PLCI	12451	UTCI	43950	1980	23,454
PLCI	12452	UTCI	43951	1980	23,454
PLCI	12453	UTCI	43952	1980	23,454
PLCI	12454	UTCI	43953	1980	23,454
PLCI	12455	UTCI	43954	1980	23,454
PLCI	12456	UTCI	43955	1980	23,454
PLCI	12457	UTCI	43956	1980	23,454
PLCI	12458	UTCI	43957	1980	23,454
PLCI	12459	UTCI	43959	1980	23,454
PLCI	12460	UTCI	43960	1980	23,454
PLCI	12461	UTCI	43961	1980	23,454
PLCI	12462	UTCI	43962	1980	23,454
PLCI	12463	UTCI	43963	1980	23,454
PLCI	12464	UTCI	43964	1980	23,454
PLCI	12465	UTCI	43965	1980	23,454
PLCI	12466	UTCI	43966	1980	23,454
PLCI	12467	UTCI	43968	1980	23,454

PLC CAR NUMBER	UNION TANK CAR NUMBER	STAP BUREAU	COST
PLCX 12468	UTCI 43370	1980	23,454
PLCX 12469	UTCI 43371	1980	23,454
PLCX 12470	UTCI 43372	1980	23,454
PLCX 12471	UTCI 43373	1980	23,454
PLCX 12472	UTCI 43374	1980	23,454
PLCX 12473	UTCI 43375	1980	23,454
PLCX 12474	UTCI 43376	1980	23,454
PLCX 12475	UTCI 43377	1980	23,454
PLCX 12476	UTCI 43378	1980	23,454
PLCX 12477	UTCI 43379	1980	23,454
PLCX 12478	UTCI 43380	1980	23,454
PLCX 12479	UTCI 43381	1980	23,454
PLCX 12480	UTCI 43382	1980	23,454
PLCX 12481	UTCI 43383	1980	23,454
PLCX 12482	UTCI 43384	1980	23,454
PLCX 12483	UTCI 43385	1980	23,454
PLCX 12484	UTCI 43386	1980	23,454
PLCX 12485	UTCI 43387	1980	23,454
PLCX 12486	UTCI 43388	1980	23,454
PLCX 12487	UTCI 43389	1980	23,454
PLCX 12488	UTCI 43390	1980	23,454
PLCX 12489	UTCI 43391	1980	23,454
PLCX 12490	UTCI 43392	1980	23,454
PLCX 12491	UTCI 43393	1980	23,454
PLCX 12492	UTCI 43394	1980	23,454
PLCX 12493	UTCI 43395	1980	23,454
PLCX 12494	UTCI 43396	1980	23,454
PLCX 12495	UTCI 43397	1980	23,454
PLCX 12496	UTCI 43398	1980	23,454
PLCX 12497	UTCI 43399	1980	23,454
PLCX 12498	UTCI 44341	1980	23,454
PLCX 12499	UTCI 44342	1980	23,454
PLCX 12500	UTCI 44343	1980	23,454
PLCX 12501	UTCI 44344	1980	23,454
PLCX 12502	UTCI 44345	1980	23,454
PLCX 12503	UTCI 44346	1980	23,454
PLCX 12504	UTCI 44347	1980	23,454
PLCX 12505	UTCI 44348	1980	23,454
PLCX 12506	UTCI 44349	1980	23,454
PLCX 12507	UTCI 44350	1980	23,454
PLCX 12508	UTCI 44351	1980	23,454
PLCX 12509	UTCI 44352	1980	23,454
PLCX 12510	UTCI 44353	1980	23,454
PLCX 12511	UTCI 44354	1980	23,454
PLCX 12512	UTCI 44355	1980	23,454
PLCX 12513	UTCI 44356	1980	23,454
PLCX 12514	UTCI 44357	1980	23,454
PLCX 12515	UTCI 44358	1980	23,454
PLCX 12516	UTCI 44359	1980	23,454
PLCX 12517	UTCI 44360	1980	23,454

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST	
PLCI 12510	UTC1	43094	1980	23,454
PLCI 12519	UTC1	43095	1980	23,454
PLCI 12520	UTC1	43096	1980	23,454
PLCI 12521	UTC1	43097	1980	23,454
PLCI 12522	UTC1	43099	1980	23,454
PLCI 12573	UTC1	43048	1980	23,454
PLCI 12574	UTC1	43081	1980	23,454
PLCI 12575	UTC1	43092	1980	23,454
PLCI 12576	UTC1	43095	1980	23,454
PLCI 12527	UTC1	43101	1980	23,454
PLCI 12528	UTC1	43106	1980	23,454
PLCI 12529	UTC1	43107	1980	23,454
PLCI 12530	UTC1	43109	1980	23,454
PLCI 12531	UTC1	43110	1980	23,454
PLCI 12532	UTC1	43128	1980	23,454
PLCI 12533	UTC1	43129	1980	23,454
PLCI 12534	UTC1	43133	1980	23,454
PLCI 12535	UTC1	43134	1980	23,454
PLCI 12536	UTC1	43135	1980	23,454
PLCI 12537	UTC1	43136	1980	23,454
PLCI 12538	UTC1	43137	1980	23,454
PLCI 12539	UTC1	43139	1980	23,454
PLCI 12540	UTC1	43141	1980	23,454
PLCI 12541	UTC1	43143	1980	23,454
PLCI 12542	UTC1	43153	1980	23,454
PLCI 12543	UTC1	43154	1980	23,454
PLCI 12544	UTC1	43160	1980	23,454
PLCI 12545	UTC1	43163	1980	23,454
PLCI 12546	UTC1	43166	1980	23,454
PLCI 12547	UTC1	43170	1980	23,454
PLCI 12548	UTC1	43171	1980	23,454
PLCI 12549	UTC1	43173	1980	23,454
PLCI 12550	UTC1	43175	1980	23,454
PLCI 12564	UTC1	43950	1980	23,454
PLCI 12565	UTC1	43977	1980	23,454
PLCI 12633	UTC1	44940	1980	23,454
PLCI 12634	UTC1	44973	1980	23,454
PLCI 12635	UTC1	44975	1980	23,454

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCI 12636	UTCI 44976	1980	23,454
PLCI 12637	UTCI 44977	1980	23,454
PLCI 12638	UTCI 44978	1980	23,454
PLCI 12639	UTCI 44980	1980	23,454
PLCI 12640	UTCI 44981	1980	23,454
PLCI 12642	UTCI 44984	1980	23,454
PLCI 12643	UTCI 44985	1980	23,454
PLCI 12644	UTCI 44986	1980	23,454
PLCI 12645	UTCI 44988	1980	23,454
PLCI 12646	UTLI 220001	1980	23,454
PLCI 12646	UTLI 220002	1980	23,454
PLCI 12647	UTLI 220003	1980	23,454
PLCI 12648	UTLI 220004	1980	23,454
PLCI 12649	UTLI 220005	1980	23,454
PLCI 12650	UTLI 220006	1980	23,454
PLCI 12651	UTLI 220007	1980	23,454
PLCI 12652	UTLI 220008	1980	23,454
PLCI 12653	UTLI 220009	1980	23,454
PLCI 12654	UTLI 220010	1980	23,454
PLCI 12655	UTLI 220011	1980	23,454
PLCI 12656	UTLI 220012	1980	23,454
PLCI 12657	UTLI 220013	1980	23,454
PLCI 12658	UTLI 220014	1980	23,454
PLCI 12659	UTLI 220015	1980	23,454
PLCI 12660	UTLI 220016	1980	23,454
PLCI 12661	UTLI 220017	1980	23,454
PLCI 12662	UTLI 220018	1980	23,454
PLCI 12663	UTLI 220019	1980	23,454
PLCI 12664	UTLI 220020	1980	23,454
PLCI 12665	UTLI 220021	1980	23,454
PLCI 12666	UTLI 220022	1980	23,454
PLCI 12667	UTLI 220023	1980	23,454
PLCI 12668	UTLI 220025	1980	23,454
PLCI 12669	UTLI 220026	1980	23,454
PLCI 12670	UTLI 220027	1980	23,454
PLCI 12671	UTLI 220028	1980	23,454
PLCI 12672	UTLI 220029	1980	23,454
PLCI 12673	UTLI 220030	1980	23,454

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCI 12633	UTL1 220031	1900	23,434
PLCI 12636	UTL1 220032	1900	23,434
PLCI 12637	UTL1 220033	1900	23,434
PLCI 12638	UTL1 220034	1900	23,434
PLCI 12639	UTL1 220035	1900	23,434
PLCI 12700	UTL1 220036	1900	23,434
PLCI 12701	UTL1 220037	1900	23,434
PLCI 12702	UTL1 220038	1900	23,434
PLCI 12703	UTL1 220039	1900	23,434
<hr/>			
5,558,598			
<hr/>			

PLC CAR NUMBER	UNION TANK CAR NUMBER	YEAR BUILT	COST
PLCI 12440	UTLX 220078	1981	24,942
PLCI 12441	UTLX 220088	1981	24,942
PLCI 12442	UTLX 220089	1981	24,942
PLCI 12443	UTLX 220093	1981	24,942
PLCI 12444	UTLX 220096	1981	24,942
PLCI 12445	UTLX 220097	1981	24,942
PLCI 12446	UTLX 220098	1981	24,942
PLCI 12447	UTLX 220099	1981	24,942
<hr/>			
199,536			
<hr/>			